

While riding the Rubicon Trail near Lake Tahoe, Radek Burkat and friends experienced a skid plate failure resulting in catastrophic damage to a KTM990 motor casing. Here are photos to illustrate what happened.



This guy now has a **Black Dog Cycle Works** plate on his bike.
Think twice before buying another brand of "cosmetic" bike armor.



The bikes with BDCW skid plates made it back unscathed.



Black Dog
CYCLE WORKS™

The ULTIMATE armor for your bike • BlackDogCW.com